

Announcing - Obsolescence Elo Touch Monitor

Obsolete and Replacement Products.

Listed below are the affected Elo part numbers and the recommended replacement parts.

Obsolete Part Number N description	Recommended Replacement Part Number				
1515L obsolete list: Only P CAP, Accutouch and Intellitouch touch technology will remain					
E538481 1515L with APR	E291747 1517L with iTouch in White				
E557524 1515L with APR	or				
E176383 1515L with APR	E953836 1517L with iTouch in Black				
1522L Obsolete list. Only 1522L Intellitouch and Accutouch both in Gray color still available. But					
recommend to change to 1517L platform. Or1523L platform					
E993389 1522L With Accutouch					
E407449 1522L With Accutouch	E247852 1517L with Accutouch				
E136451 1522L With Accutouch					
E889598 1522L With Intellitouch					
E664329 1522L With Intellitouch					
E626377 1522L With Intellitouch					
E592262 1522L With Intellitouch	E291747 1517L with I Touch White color				
E337897 1522L with Carroll Touch	or				
E195812 1522L with Carroll Touch	E953836 1517L with I Touch Gray color				
E576670 1522L with Carroll Touch					
E869591 1522L with APR					
E317038 1522L with APR					
E460428 1522L with APR					
E172222 1522L with APR					
1529L Obsolete List. Only 1522L Intelli	touch and Accutouch both available, will be replaced by				
1523L					
E564135 1529L with Intellitouch	E953836 1517L with I touch				
E580588 1529L with Intellitouch	or				
E392726 1529L with Carroll Touch	E394454 1523L I touch Plus . Both in Black color.				
E353946 1529L with APR					
E680845 1529L with APR					
1715L Obsolete list, Only P CAP, Accuto	ouch and Intellitouch				
E441167 1715L with APR	E928533 1717L with I Touch in Black or E854392 in				
E832132 1715L with APR	White				
1729L Obsolete list. Only 1729L Intellitouch and Accutouch both in Gray color still available.					
E523806 1729L with Carroll Touch					
E555423 1729L with Carroll Touch	E650075 1717L with Accutouch in White or E433551 in Black				
E645806 1729L with APR					
E403890 1729L with APR					

Data Asia Newsletter Sept, 2013.

1919L APR replace by other technology				
E459829 1919L APR	Pls check with 1919L other touch technology			
1919LM APR replace by IntelliTouch				
E956891 1919LM with APR	Pls check 1919LM other touch technology			
1928L APR replace by IntelliTouch				
E850529	E897317 1928L intellitouch			

Obsolete Part Number	Recommended Replacement Part Number			
All open frame monitor APR replace by IntelliTouch				
E005652 1537L with Al	PR	E512043	1537L with Intellitouch	
E630566 1739L with Al	PR	E012584	1739L with Intellitouch	
E381864 1939L with AF	PR	E896339	1937L with Intellitouch	
E216403 1939L with AF	'R	E215546	1939L with Intellitouch	
E091985 2239L with Al	PR	E654071	2239L with Intellitouch	
E461971 2239L with AF	'R			
E304159 2243L with Al	PR	E059181	2243 L with Intellitouch	
E738068 2244L with A	PR	E469590	2244L with Intellitouch	

When products are obsolete, every effort is made for a smooth transition. Please contact us to quote on new replacement models. There are new selections to choose from so let us know your old part no. and we can help you transfer to a new platform.

For further details on our products, please feel free to contact us @ +852-25440899 or +852-25434921, or via email to sales@touchscreen.com.hk Marketing Department: Website: http://www.touchscreen.com.hk

If you want to unsubscribe to our newsletter, please inform us by a return email!